

466




FIG 1

09098614-041798

PRINT OF DRAWINGS
AS ORIGINALLY FILED





FIG. 2

090036514 - 051290

二〇一九年九月一日

Bulletin Gateway Architecture Block Diagram



TWS Inc

2/10/98

FIG. 3




FIG. 4




Fig. 5

002700-00-14-1998060

**PRINT OF DRAWINGS
AS ORIGINALLY FILED**




FIG. b

**PRINT OF DRAWINGS
AS ORIGINALLY FILED**





FIG. 7

00000000000000000000000000000000

Bu



F15, 8

Message Transmission Failure




FIG. 9

09098614 - 061798

**PRINT OF DRAWINGS
AS ORIGINALLY FILED**




FIG. 10

SMSC communication
MAGsms Initialization





FIG. 11

600790-1416060


862790-4159600

FIG. 12




8627190-41786060

FIG 13



00000000000000000000000000000000


FIG 14




**PRINT OF DRAWINGS
AS ORIGINALLY FILED**

00003514-1990-06050


FIG. 15






**PRINT OF DRAWINGS
AS ORIGINALLY FILED**

17
16741-17036060




**PRINT OF DRAWINGS
AS ORIGINALLY FILED**

FIGURE 18
1801 1802 1802A 1803 1803A 1804 1805 1806 1807 1808 1809




**PRINT OF DRAWINGS
AS ORIGINALLY FILED**



8627500-4 T 20000

**PRINT OF DRAWINGS
AS ORIGINALLY FILED**



86274790-4149860000

**PRINT OF DRAWINGS
AS ORIGINALLY FILED**

FIG 21

00000000000000000000000000000000

